

Cristian Perez

Subject: Inspection Log

Start: Mon 08/15/2022 9:00 AM
End: Mon 08/15/2022 4:30 PM

Recurrence: Weekly
Recurrence Pattern: every Monday and Tuesday from 9:00 AM to 4:30 PM

Organizer: Cristian Perez

1.	RAVELLO	LOT 01.A	B22-00988	ROOF SHR	AM	ON SITE
2.		LOT 01.B	B22-01049	ROOF SHR	AM	ON SITE
3.		LOT 02.A	B22-00998	ROOF SHR	AM	ON SITE
4.		LOT 02.B	B22-01050	ROOF SHR	AM	ON SITE
5.		LOT 03.A	B22-00999	ROOF SHR	AM	ON SITE
6.		LOT 03.B	B22-01051	ROOF SHR	AM	ON SITE
7.		LOT 12	B21-00231	U/G PLUMBING	AM	ON SITE
8.		LOT 01.A	B22-00693	MEPS	AM	ON SITE
9.		LOT 01.B	B22-00782	MEPS	AM	ON SITE
10.		LOT 02.A	B22-00694	MEPS	AM	ON SITE
11.		LOT 02.B	B22-00783	MEPS	AM	ON SITE
12.	E AVENUE S-2		B22-01506	PV F	10-2	ON SITE
13.	CASABA TERRACE		B22-01568	PV F	10-2	ON SITE
14.	RUBY RED LN		E22-00241	EV CHARGER F	10-2	ON SITE
15.	TUCSON CT		M22-00080	MECH F	PM	ON SITE
16.	ZINFANDEL DR		B21-02637	PRE-PLASTER	PM	ON SITE
17.	W AVENUE M-4		B21-01792	INSULATION	PM	ON SITE
18.	NIDO CT		B22-02254	PRE-DEMO POOL	PM	ON SITE
19.	PRESTON RD		B22-01844	PV F	PM	ON SITE
20.	DENHAM DR		B22-02067	PV F	PM	ON SITE
21.	CASTANA LN		M22-00345	MECH F	PM	ON SITE
22.	AVIGNON LN		B22-02124	PV F	PM	ON SITE
23.	MYRTLE ST		E22-00232	MSP/ U	PM	ON SITE
24.	FOLLOW UP ON COMPLAINTS / REPORTS			COMP	PM	ON SITE

Raul Guzman

Subject: 08/15/2022 Inspections
Start: Mon 08/15/2022 9:00 AM
End: Mon 08/15/2022 4:30 PM
Recurrence: (none)

1. E Ave Q-1	B22-01884	Drywall	9-1
2. Pac Comm	B22-01621	Roof	9-1
3.	B21-00206	Ret Wall	9-1
4. Trilport Ave	B22-02050	PV-F	9-1
5. Verdon St	P22-00201	Patio	10-2
6. Versailles St	B22-01678	Pool	10-2
7. Whitney Way	B21-02260	Final	10-2
8. Katrina Pl	B22-02037	Plumb	10-2
9. 37 th St E	B22-00199	Pool	10-2
10. 36 th St E	B22-01781	Elect	1-4:30
11. E Ave R-8	B22-01131	F-PV	1-4:30
12. Sparkling Water	B22-02497	Remod	1-4:30
13. E Ave P-5	B22-02394	Final	1-4:30

George Schneider

Subject: Today's inspections:
Start: Mon 08/15/2022 12:00 PM
End: Mon 08/15/2022 12:30 PM
Recurrence: (none)

Today's inspections:

1. Ave R/Division	Combo	B19-01618	AM	On-site
2. Falset St/10 th	Roof nailing	B20-00130	AM	On-site
3. GUITA CT/30 th	Hot mop	B22-02430	AM	On-site
4. NIDO CT/50 th	Ret Wall	B22-00468	AM	On-site
5. Myrtle St/60 th	Pre-wrap	B21-02076	PM	On-site
6. CIELO VISTA DR/65 th	Gas test	B21-02270	PM	On-site
7. CIELO VISTA DR/65 th	Gas test	B21-02271	PM	On-site
8. CIELO VISTA DR/65 th	Gas test	B21-02272	PM	On-site
9. CIELO VISTA DR/65 th	Gas test	B21-02274	PM	On-site
10. CIELO VISTA DR/65 th	Insulation	B21-02307	PM	On-site

Dustin Gerbitz

Start: Mon 08/15/2022 8:30 AM

End: Mon 08/15/2022 4:30 PM

Recurrence: Weekly

Recurrence Pattern: every Monday, Tuesday, Wednesday, and Thursday from 8:30 AM to 4:30 PM

Organizer: Dustin Gerbitz

- | | | | |
|---------------------------|-----------|----------|----|
| 1. Rancho Vista Park Walk | B19-01924 | Final | AM |
| 2. City Yard | B20-01940 | Car Wash | PM |
| 3. 6455 Shayna Court | B17-01023 | Lath | PM |

Jason Dannenfelser

Subject: INSPECTIONS

Start: Mon 08/15/2022 11:00 AM
End: Mon 08/15/2022 11:30 AM

Recurrence: Weekly
Recurrence Pattern: every Monday, Tuesday, Wednesday, and Thursday from 11:00 AM to 11:30 AM

Organizer: Jason Dannenfelser

1.	BOXTHORN ST	HVAC	M22-00199	9-12	ONSITE
2.	KARLING PL	PV W/MSP	B22-01326	9-12	ONSITE
3.	SUMMERHOLLY	PV W/MSP	B22-01278	9-12	ONSITE
4.	LILACVIEW	MSP	E22-00119	9-12	ONSITE
5.	JENNIFER DR	PV W/MSP	B22-00449	9-12	ONSITE
6.	E AVE R-5	PV W/MSP	B21-03080	11-2	ONSITE
7.	27 TH ST E	ROOF SHEATH	B22-02189	11-2	ONSITE
8.	DALZELL ST	PV	B22-02111	11-2	ONSITE
9.	DUOMO ST	POOL	B22-00801	11-2	ONSITE
10.	ERICK CT	HVAC	M22-00076	12-4	ONSITE
11.	PEONZA LN	MSP	E22-00187	12-4	ONSITE
12.	CHARDONNAY AVE	PV	B22-01685	12-4	ONSITE

Wilber Rosales

Subject: Inspection Log
Start: Mon 08/15/2022 9:00 AM
End: Mon 08/15/2022 4:30 PM
Recurrence: (none)

1. Oakmont Ct.	M22-00312	Mech F	AM	OnSite
2. Makin Ave.	B22-02090	PV F	AM	OnSite
3. E Avenue P5	B22-01745	PV F	AM	OnSite
4. Division St.	M22-00295	Mech F	AM	OnSite
5. E Avenue P4	B22-02184	Roof Shr	10-2	OnSite
6. Maureen St.	B22-01992	PV F	10-2	OnSite
7. Simsbury St.	B22-02428	Roof F	10-2	OnSite
8. Lemsford Ave.	B22-01432	PV F	10-2	OnSite
9. Royce Ct.	B22-01849	PV F	10-2	OnSite
10. Barcelona Dr.	P22-00185	WH/CO	10-2	OnSite
11. Lisbon Ct.	B22-02208	PV F	10-2	OnSite
12. E Avenue Q12	B22-01952	PV F	PM	OnSite
13. Barletta Ct.	M22-00311	Mech F	PM	OnSite
14. Follow-up Complaints		Complaints	PM	OnSite

AM: 9am-12pm

PM: 12pm-4:30pm